

CONVERSION D'UNITE DE PRESSION.

368 bytes.

```

"UNIT.DE PRESS"
Lb1 0
"VAL.DE PRESS"
?→A
Lb1 1
"NO.UNITE"
"BAR=1"
"PAS=2"
"DAN/MM²=3"
?→B
If B>3 Or B<1
Then Goto 1
IfEnd
Lb1 2
"NO.APRES CONVER"
?→C
If C>3 Or C<1 Or C=B
Then Goto 2
IfEnd
If B=1:Then Goto 3
IfEnd
If B=2:Then Goto 4
IfEnd
If C=1:Then Goto 5
IfEnd
E7A→D,
"PA",
Goto 0
Lb1 5
100A→D,
Goto 9
Lb1 4
If C=1:Then Goto 6
IfEnd
E-7A→D,
Goto 8
Lb1 6
E-5A→D,
Goto 9
Lb1 3
If C=2:Then Goto 7
IfEnd
A/100→D,
Goto 8
Lb1 7
E5A→D,
"PA",
Goto 0
Lb1 8
"DAN/MM²",
Goto 0
Lb1 9
"BAR OU DAN/CM²",
Goto 0

```